

Jim MacArthur's Electronics Shop
Cruft 219

- some clutter, but Jim is looking for storage space
- GE varnish in secondary containment, but it should really be in a flammables cabinet
- Jim needs to take the Hazmat safety training course

Capasso group
Cruft 312

- no safety shower, but this is ok because the lab will be moved to McKay in a couple months time anyway
- fire extinguisher last inspected in 2005

Hau group
Cruft 115, 116, 110, 110, 23

- updated chemtracker sheets needed for emergency contact
- suggest emergency EHS flip-charts be posted
- fire extinguisher in Cruft 23 last inspected in 2001!

MD 313

- electrical panel (breaker box) access blocked by a large table
- needs emergency contact sign (chemtracker)
- suggest there be a flip-chart of EHS info as well

Ham group (MD 315, B133)

MD 315

- needs emergency contact sign (chemtracker)
- suggest there be a flip-chart of EHS info as well
- could use a fire extinguisher
- should label fridge for bio samples with "no storage of food"

MD B133

- needs emergency contact sign (chemtracker)
- suggest there be a flip-chart of EHS info as well
- needs a fire extinguisher
- don't block the eyewash station (pump was in front of it)
- store extra chemicals in hood rather than on tables

MD B130

- seems to be an instructional laser lab, not clear who's responsible for it